



Federal Aviation Administration

OKLAHOMA CITY ATCT
4500 S.W. 67TH STREET
OKLAHOMA CITY, OK 73159

=====

ISSUED: SEPTEMBER 27, 2011

EFFECTIVE: OCTOBER 1, 2011

LETTER TO AIRMEN NO. 11-1

SUBJECT: PRACTICE INSTRUMENT APPROACHES

CANCELLATION: SEPTEMBER 30, 2013

This letter supersedes Oklahoma City ATCT Letter to Airmen No. 09-1 issued October 1, 2009.

In the interest of flight safety this letter is issued in response to inquiries concerning ATC separation standards applied to VFR flights conducting practice instrumentation approaches.

Standard IFR separation shall be provided to VFR aircraft, not on an IFR flight plan, practicing instrument approaches to Will Rogers, Wiley Post, Max Westheimer, Sundance, Clarence E. Page, and Tinker AFB. This separation commences upon issuance of the approach clearance by the controller. Except for heavy aircraft/B757, 500 feet vertical separation may be applied between VFR aircraft and between a VFR and IFR aircraft.

For procedural application and understanding, pilots are encouraged to review the section of the AIM, concerning PRACTICE INSTRUMENT APPROACHES. VFR aircraft can expect to receive altitude assignments and vectors for sequencing in the approach pattern, but should remember that it is the pilot's responsibility to conduct all phases of the flight in VFR weather conditions. If a control instruction cannot be accepted due to weather considerations, inform the controller immediately.

The least busy traffic periods at Will Rogers are between 11:30 a.m. and 1:30 p.m. and after 9:00 p.m. Pilots practicing approaches to Max Westheimer are reminded to be especially alert for the possibility of opposite direction traffic on runway 21. The wide range of approach speeds for aircraft which utilize our airports is the most common reason for vector delays when practice approaches are conducted. Your continued understanding and cooperation are most appreciated.

Using Will Rogers Airport as a reference point, practice approaches should call on the following frequencies: West 124.6, Northeast 124.2, Southeast 120.45.

If you have any questions regarding this letter please call (405) 686-4700 during normal business hours 8:00 a.m. to 4:00 p.m.

A handwritten signature in cursive script, appearing to read "Denise L. Beck", is located above the printed name.

Denise L. Beck
Air Traffic Manager
Oklahoma City ATCT